

100

110

F	F	F	F	F	3.3
F	F	F	F	F	3.3165
F	F	F	F	F	3.333
F	F	F	F	F	3.3495
F	F	F	F	F	F	3.366
F	F	F	F	F	F	F	3.3825
F	F	F	F	F	F	F	F	.	.	.	3.399
F	F	F	F	F	F	F	F	F	.	.	3.4155
F	F	F	F	F	F	F	F	F	F	.	3.432
F	F	F	F	F	F	F	F	F	F	F	3.4485
F	F	F	F	F	F	F	F	F	F	F	3.465
1	1	1	1	1	1	1	1	1	1	1	
7	7	7	7	7	7	7	7	7	7	8	
1	1	2	3	4	5	6	7	8	9		
	9	8	7	6	5	4	3	2	1		

FIRST
OPERATING
PARAMETER


SECOND
OPERATING
PARAMETER

Fig. 1
Prior Art

10020039-000501

250

StartPoint=(1.45000, 3.50000)
 HorizontalStepSize=0.05000 VerticalStepSize=0.05000
 HorizontalRange 1.00000 - 2.50000 VerticalRange 2.00000 - 4.60000



Second
 Operating
 Parameter
 220

1 1 1 1 1 1 1 1 1 2 2 2 2 2 2 2 2
 5 3 6 6 7 8 8 8 9 9 0 0 1 1 2 2 3 3 4
 0 5 0 5 0 5 0 5 0 5 0 5 0 5 0 5 0 5 0
 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

First Operating Parameter

Points Tested = 130

210

Fig. 2




Fig. 3




Fig. 4